

Prioritizing barrier removals in Germany –

a GIS and feasibility approach

Dr. Ruben van Treeck, WWF Germany



Background

- **The big picture**: Beletti et al. (2020) estimate 200k barriers in Germany
- (obsolete) barriers are expensive to maintain, can be a safety hazard & prevent the WFD-"good state"
- Political frameworks strive to improve river connectivity (EU Biodiversity Strategy/NRL, German legislation and action plans)
- Federal republic with 16 states
- Across-state perspectives hard to come by









2: Location within catchment













Dr. Ruben van Treeck | Prioritizing barrier removals in Germany - a GIS and feasibility approach | FreeFlow 2024



Look up ~20 high-level barriers/state, find out

- Their condition
- Whether infrastructure in vicinity prevents lowering water level
- If they belong to something (someone?) special
- Their purpose (hydro, navigation, agriculture, flood prevention...)
- If a removal may already be considered (WFD!)



Also, identify responsible authority, get in touch and ask for assessment



Results

Barrier portfolio with clear ecological potential and "fuzzy" removability assessment.



Neu angeschlossene Fließgewässerstrecke

Arten im FFH-Gebiet

Bachmuschel

Bachneunauge

Groppe

Positive Folgen nach Rückbau

Wenn das vorhandene Sohlenbaur durchgängiges Bauwerk ersetzt werden eine Strecke von 47,9 km oberhalb des I Gewässerfauna neu erschlossen werden.

Schutzgebiet

Das Querbauwerk, sowie auch größere Flächen der neu angebundenen Strecken liegen innerhalb des FFH-Gebiets Stepenitz (DE 2738-302). Das FFH-Gebiets weist einen hohen Anteil weitgehend unbeeinflusster Gewässerabschnitte mit natürlicher Auendynamik auf. Es zählt zu den ökologisch bedeutsamsten und am besten erhaltenen Fließgewässersystemen in Brandenburg. (MLUK 2015)

WOLFSHAGENER WEHR

Gewässer: Steper in Brandanhurr

Situation heute:

Seit dem Ausbau der Turbinen wird die Stauhaltung nicht weiter benötigt. Das Wehr in der Stepenitz wurde zu einer Sohlrampe mit einem Raugerinne-Beckenpass umgestaltet. Das Bauwerk wurde jedoch nach fachgutachterlicher Betrachtung als selektiv wirkend eingestuft, da die Wassertiefe zu niedrig ist, die Länge der Becken zu kurz und die Durchlassbreite zu gering. (MLUK 2024)

ALTONIA DAMAGE IN

Fischotter Kammmolch Bauchige Windelschnecke

Schmale Windelschnecke

Derzeitiges Sohlenbauwe

11



Shout out to

our contractors

Uli Schwarz (Fluvius, Vienna)

Rita Keuneke, Pia Bünis (FWT Aachen)

Rainer Bonn, Uwe Koenzen (Planungsbüro Koenzen)

Sigrun Lange (WWF Germany)







Methodological limitations of pure-GIS analysis

- Consecutive barriers with great combined yield may be overlooked
- Large reconnection potential in big streams may mask habitat quality & potential for large-scale restoration programmes
- Lateral connectivity is not assessed